-Vehicle Inspection Complete | Texas.gov

https://dpsdirect.portal.texas.gov/vicinspect/VehicleInspectionComplet..

Vehicle Inspection Connection (VIC)

7024

dps logo Texas Department of Public Safety

Vehicle Inspection Report

Authorization Code: 4HN9R91U4993Z

PLEASE RETAIN FOR YOUR RECORDS

Federal Motor Carrier Safety Regulation Compliance

I have performed the annual inspection of the referenced vehicle, which is accurate, complete and in accordance with the inspection criteria set forth in 49C.F.R. Chapter 396.17 through 396.21

Overall Result:	Pass	Fees	
Test Date/Time:	05/22/2024 09:44 PM	Inspection Fee:	\$40.00
Inspection Class:	CDEC	Repair Cost:	\$0.00
Inspection Exp Date:	05/31/2025	Total:	\$40.00

Vehicle	Inform	ation

Station	Informa	tion
Station	THIUITHA	uvu

VIN:	1JJV532W87L055550	Station #:	2P041487
License Number:	TX 156B343	Station Name:	ALLGAYERS BIG RED, LLC
Registration County:	WHARTON	Station Address:	1250 E JACKSON
Vehicle Type:	Trailer		EL CAMPO, TX 77437
Year:	2007	Inspector Name:	GILBERTO VELA
Make:	WABASH		
Model:	TRAILER	Inspection Information	
Fuel Type:	None	Inspection Type:	COMMERCIAL/DECAL
Odometer Reading:		Test Type:	INITIAL
Insurance Exp:	09/05/2024	Affidavit Type:	
_			

Insurance Mileage Exp:

I certify that I have properly performed the vehicle inspection according to the state regulations and procedure manuals, and as the undersigned duly appointed inspector, hereby certify that I have physically examined the manufacturer's vehicle identification number of the motor vehicle described above.

Certified Inspector Signature

Date